



Certificate no.

**QISJ4/OSA-RWI-239046**

Date of Issue

**22, April, 2026**

## **CERTIFICATE OF ROADWORTHINESS**

**KS1515:2000**

We hereby certify that the motor vehicle whose details are given below was inspected by Quality Inspection Services Japan and found to conform to the requirements of KS1515:2000

### **INSPECTION INFORMATION**

Country of Supply

**JAPAN**

Inspection Center

**OSAKA**

Inspection Date

**21, April, 2026**

### **INSPECTED MOTOR VEHICLE PARTICULARS**

Make

**PEUGEOT 3008**

Model

**3BA-P845G06 2WD**

Chassis/VIN Number

**VF3M45GFRKS351131**

Engine Number/Model

**5G06 - 2576762**

Engine Capacity(c.c Rating)

**1590 cc**

Year of Manufacture

**-**

Year of First Registration

**2019/10**

Inspected Mileage (Odometer Reading)

**29910 km**

#### **Remarks:**

The radiation level on this vehicle was surveyed and found to be within the internationally accepted limits at the time of inspection.

This certificate issued under the authority of Pre-export Verification of Conformity Program for and on behalf of Kenya Bureau of Standards, KENYA and is valid for a period of 90 days from the date of issuance. No responsibility will be assumed for any alteration made to the vehicle after completion of the inspection.

This document does not discharge exporters from their contractual obligations in relation to quality of the motor vehicle referred to herein nor does it discharge the importer or exporter from exercising all their rights and discharging all their liabilities under the contract of sale. KEBS may reject the vehicle covered by this certificate if found to be non-conforming on verification at the port of entry.

#### **CERTIFICATE EXPIRATION DATE**

**20, July, 2026**

**QUALITY INSPECTION SERVICES JAPAN**

Authorized Signatory: